LOTUS Cars USA, Inc.

Service Letter

JANUARY 14, 2000

TO: ALL LOTUS DEALER PARTS AND SERVICE DEPARTMENTS

SUBJECT: PART NUMBER A100B0661F CLIP – WINDSCREEN FINISHER

THE ORIGINAL STOCKS OF P/N **A100B0661F** HAVE BEEN EXHAUSTED. THE PART CURRENTLY BEING SUPPLIED IS IN AN "UNTRIMMED" CONDITION. THE CURRENT PART SUPPLIED CONSISTS OF "TWO" A100B0661F CLIPS FORMED TOGEATHER. THE DIAGRAM BELOW PROVIDES A GENERAL IDEA AS TO HOW THE PIECE SHOULD BE TRIMMED. **NOTE:** ON THE UNDERSIDE OF THE SUPPLIED PART THERE ARE PATTERN MARKS TO ASSIST IN THE FABRICATION.

AS SUPPLIED

